TECHNICAL EVALUATION REPORT (As Per Rule 35 of PP Rules, 2004) MULTAN ELECTRIC POWER COMPANY LTD, MULTAN Name of Procuring Agency: 1. Single Stage Two Envelope Method of Procurement: 2. Title of Procurement: For the procurement of Misc. Items 3. Tender No.26/2024-25 Tender Inquiry No.: 4. PPRA Ref. No.(TSE): TS546053E. 5. ١. Date & Time of Bid Closing: 24.09.2024 at 11:45 6. Date & Time of Bid Opening: 24.09.2024 at 12:15 7. No of Bids Received: Six (06) 8. Criteria for Bid Evaluation: As per bidding document 9. Details of Bid(s)Evaluation: As under:-10. Rule/Regulation/SBD*/Policy/ Basis for Technical Technical Rejection / Acceptance as per Rule 35 of PP Rules, 2004. Name of Bidder Marks (if applicable) Due to following reasons:-1. The bidder has attached unfilled standard forms (Bidder's Manufacturer's Experience of supply record & Bidder's Manufacture's Performance Record) as required in Section-VI (Standard Forms) of bidding documents. 2. The Bidder has not submitted supply record of AB Powder (Lot-II) with bid as laid down in Clause 10(1), Section-III of bidding documents. 3. The bidder does not meet 05-years design / manufacturing M/s Shah Gee Enterprises (Pvt) Ltd Nonexperience of AB Powder (Lot-II) & H V Detector (Lot-III & IV) as laid down in clause 10 (2), Section-III of bidding Responsive Lahore documents. 4. The bidder has not attached at least two satisfactory operational certificates alongwith relevant purchase Orders with bid of quoted Item. Therefore, the bidder does not meet the performance criteria as laid down in clause 10(3) section,-III of bidding documents. 5. The bidder has not attached Test reports of offered HV Detectors as required in clause 5, Section-V of bidding documents. Due to following reasons. 1. Supply record of offered AB Powder of last five years of manufacturer to establish the 70% quantity (Purchase orders

Non-

Responsive

Non-

Responsive

M/s Attique Corporation Lahore

M/s Bismillah Enterprises Lahore

attached with bid are of other than offered material).

1. The bidder has attached unfilled Standard forms (Bidder's

2. The bidder has not submitted supply record to establish the

3. The Bidder Does not meet 05-years design/ manufacturing

4. The bidder has not attached at least two satisfactory

5. The bidder has not attached with bid test reports of offered,

HV Detectors as required in clause 5, section-V of bidding

experience of all quoted items as laid down in clause 10(2),

operational certificates and relevant purchase orders with bid of quoted items. Therefore, the bidder does not meet the performance criteria as laid down in clause 10(3) section-III

70% quantity of Silica Gel I(Lot-I) & HV Detectors (Lot-III &IV) with bid as required in clause 10(1), section-III of

Section-VI (Standard forms) of bidding documents.

Manufacturer's Experience of supply record & Bidder's Manufacturer's performance record) with bid as required in

1.

2. The bidder has not provided:

Due to Following reasons:-

bidding documents

of bidding documents,

documents.

Delivery Documents (GRN / IC).

section-III of bidding documents.

ii) Ender user Certificates of offered material.

Name of Bidder	Technical Marks (if applicable)	Rule/Regulation/SBD*/Policy/ Basis for Technical Rejection / Acceptance as per Rule 35 of PP Rules, 2004.
M/s Unicom Corporation Lahore	Non- Responsive	 Offered High Voltage Detector with Model 276HD (Lot-III) has working voltage range 3kV~24kV AC instead of required 02-35KV range. As per Attached authorization letter, manufacturer has authorized the bidder for supply of 276HD (Lot-III) having working range 3kV~24kV AC only not for supply of high Voltage detector for 132KV (Lot-IV) No supply record and operational certificate of high voltage detector for 132KV are found in bid. No lab test report attached in bid.
M/s JZ International Lahore	Non- Responsive	 Due to the following reasons:- The bidder has attached unfilled Standard forms (Bidder's/Manufacturer's Experience of supply record Bidder 's/manufacturer's performance record) with bid as required in section-VI (Standard forms) of bidding documents. The bidder has not attached delivery documents of relevant purchase orders with bid. Therefore the bidder does not meet the contractual experience criteria as per clause 10(1), section-III of bidding documents. The bidder has not attached delivery documents of quoted items with supplied beyond last five year to ascertain the 05-years design / manufacturing criteria s laid down in clause 10(2), Section-III of bidding documents. Therefore, manufacturer does not meet the manufacturing experience criteria. The bidder has not attached at least Two satisfactory operational certificates and relevant Purchase orders of quoted items as laid down in clause 10(3) section-III of bidding documents. Therefore, bidder / manufacturer does not meet the performance criteria.
M/s QCC Multan	Non- Responsive	Due to following reasons:- The Bidder has not provided: i) Supply record of offered AB Powder of last five year of manufacturer to establish the 70% quantity. ii) Delivery Documents (GRN / IC). iii) End User Certificates of offered Material.

Addl. Chief Engineer (Proc.)
PMU MEPCO Multan.