TECHNICAL EVALUATION REPORT

(As Per Rule 35 of PP Rules, 2004)

| 1. Name of Procuring Agency | LESCO |
|----------------------------------|--------------------------------------|
| 2. Method of Procurement | Single Stage Two Envelope |
| Title of Procurement | PTA Approved Mobile Phones (Android) |
| Tender Inquiry No. | 4132 |
| 5. PPRA Ref. No. (TSE) | TS554617E |
| 6. Date & Time of Bid Closing | 30.01.2025 10.30 a.m. |
| 7. Date & Time of Bid Opening | 30.01.2025 11.00 a.m. |
| 8. No of Bids Received | Two |
| Criteria for Bid Evaluation | As per Bidding Document |
| 10. Details of Bid(s) Evaluation | As under |

| Name of Bidder | Marks | | Evaluated | Rule/Regulation/SBD*/ Policy/Basis |
|------------------------------|-------|---------------------------|-----------|--|
| | | Financial (if applicable) | | for Rejection/ Acceptance as per Rule 35 of PP Rules, 2004. |
| M/s Riz Technology | | | - | Technically responsive bidder |
| M/s Astrontech Distributions | | | | Technically non-responsive due to following reasons: |

- While taking reading snap of meters using software MRS, mobile processor become too hot and slow due to which MRS software is not working properly causing delay in batch reading.
- 2. The mobile processing time gradually become slow after continuous use in span of one hour.
- While taking reading snaps of meters the data storage took time more than usual which causing delay and due to file storage mobile got stuck.
- The firmware is not up to the mark as per requirement of field formation i.e. not every application update compatible with mobile software in future.
- The camera quality is compromised and important specification like image resolution, image stabilization and picture quality is not up to the mark.
- 6. Picture/image quality is inferior in low light.
- 7. Mobile consumed battery more than usual using MRS software and other application.
- 8. The battery timings is not efficient as required in field for taking reading snaps of meter.
- 9. Regular updates are not available from its manufacturer.
- 10. Sensors at time start malfunctioning like brightness get increase automatically.
- 11. The mobile display is large and its screen glass is very sensitive.

Moreover the bidder has also not provided the following mandatory documents:

- i) A list of clients to whom the bidder has done similar business during last 3 years.
- ii) Stock availability certificate
- iii) Completely filled performance certificate.

| Lowest Evaluated Bidder | |
|-------------------------|--|

 Any other additional / supporting information, the procuring agency may like to share.

Endst. No. 11274 - 76

Dated: 19-03-2025

Engineer (MM) SCO Ltd, Lahore

Forwarded to the Deputy Director, Public Procurement Regulatory Authority, 1st Floor FBC Building Near State Bank, Sector G-5/2, Islamabad for uploading at PPRA Website.

Info:

1. M/s Riz Technology, Office No. 3, 2nd Floor, IT Tower, Hali Road, Gulberg-II, Lahore

 M/s Astrontech Distributions, Office No. 203, 2nd Floor, Century Tower, Kalma Chowk Flyover, Gulberg-III, Lahore