

To: PPRA
Federal Bank for Co-operative
Building 1" Floor, Near SBP
Sector G-5/2, Islamabad

Subj: **Uploading of Tender Notice Inquiry Number (IT No-1, Misc Spares) on PPRA Website**

Sealed Tenders on Single Stage ONE SEALED ENVELOPE Basis invited for the procurement of goods and services mentioned on **Annex "A"**

1. EW Base Workshop intends to purchase the items / Services as mentioned in **Anx A** to this letter.

TERMS AND CONDITIONS OF THE TENDER

2. **Rates**

- a. Quoted rates must be inclusive of all the Government taxes i.e. GST, INCOME TAX. CUSTOM DUTY AND OTHERS for
- b. **Supply of goods and services**
 - (1) Rates will be quoted for brand new stores in required Country of Origin.
 - (2) Rates will be quoted in Pak Rupees only.

3. **Quotations**. As per PPRA Rule 36 (a), Bidders submit bids in one envelope containing both the price proposal and the technical proposal.

- a. Rates to be quoted on the format provided (Soft in excel format and hard copy) otherwise quotation will not be considered, especially serial number of IT be strictly followed.
- b. No rate will be accepted through fax or any other electronic device / medium.
- c. No quotation will be accepted after prescribe time under any circumstance.
- d. No quotation will be accepted **without firm stamp on each page**.

4. Technical and Commercial Offers Must Contain Following:-

a. **Restrictions**

- (1) CUTTING OR OVERWRITING in the quotation may make it liable to rejection, therefore may be avoided.
- (2) The purchaser retains the authority to REJECT any or all the quotations as per PPRA Rules.

b. **Supply (Requirements)**

- (1) Item(s) should be exactly in accordance with part numbers, nomenclature, specifications/ samples.
- (2) Purchase orders can be issued by a third party based on this IT. Items may be required to be delivered anywhere in Pakistan at the quoted rates.
- (3) In case of machinery / equipment, the bid should include installation, training and all literature including part catalogues, owner/ user manual and repair manuals.

c. **Tender Opening**

- (1) Quotations must be dropped in the tender box before 1215 hours on **25.02.2025**.
- (2) Financial offer of only those contractors will be open whom technical will be accepted by the board and rest would be returned unopened.

d. **Important Notes**

- (1) False / wrong rates quoted in IT will be penalized by omitting complete rates in CST of said firm and seizure of bid security (Qualifying firms will be issued repeat orders, throughout the validity period of this IT.
- (2) Firms will be required to supply the ordered stores within the delivery period mentioned on the purchase order.
- (3) That procuring agency retains the right to reject a "Bid". Any "Redressal of Grievance by Contractor shall be submitted wit.

Rank: **Major**

Appointment: **OC Base Wksp**

Name: **Sehrish Naeem**

Anx A

Serial	Description (Local Spares)	Qty	Price
1.	Cashe Module	3	
2.	Smart Storage Battery	4	
3.	Complete SW Configuration from scratch	6	
4.	Cashe Module & P420 Controller	1	
5.	Internal Cashe Module	1	
6.	Smart FBWC Cashe Battery	1	
7.	Hard drive 300 GB Replacement	2	
8.	Controller card for G9 Server	1	
9.	MAINBOARD Replacement	1	
10.	Raid Control Battery	1	
11.	ROUTER – IOS updating, Network Configuration (LAN/ OSFP)	4	
12.	DDF-205 PROCESSOR BOARD REPAIR	1	
13.	GX460 Troubleshooting, image recovery firm, Firmware update, Testing, Functional Check	1	
14.	DDF-205 Synthesizer Board Repaired Firmware Update, Alignments/ Correction	1	
15.	DDF205- Repair of Processor Board- Firmware Update, Alignments/ Correctness	1	
16.	LAN Switch- POWER SUPPLY – Mother Board Faulty	1	
17.	LAN SWITCH Firmware Update, Alignments/ corrections	2	
18.	Time Server- COM Ports configuration	2	
19.	LAN Switch- 2910/24G Power Supply, Mother Board Faulty Replaced with new one	1	
20.	GX470-BIOS setting reconfigured, TPA software, re-installed/ reconfigured	1	
21.	LAN Switch-2910/24G Firmware Update, Alignments/ Corrections	1	
22.	DDF 255- Synthesizer Board Repaired	1	
23.	DDF-255 PCB Board repaired, Local Repaired, Performance Check Testing	1	
24.	DDF255- Connection Board Faulty, Repair, Installation, Testing	1	

Serial	Description (Local Spares)	Qty	Price
25.	Installation of ADD095 Antenna and Fault Rectification – Server & Laptops completely re-configured, Time Sever re-configured, 30 M cable repaired, 1 M RF Jumper replaced, Configuration of equipment as per System requirement.	1	
26.	Installation of ADD095 Antenna and Fault Rectification- Server replaced, RAMON SW reconfigured. OVP Panel repaired, CMOS port reconfigured	1	
27.	Installation of ADD095 Antenna and Fault Rectification-All server & DB server reinstallation & reconfigured.	2	
28.	Installation of ADD095 Antenna and Fault Rectification- server & windows re-installed on both SUP& IAP Laptops. RAMON S/W Installed	2	
29.	Installation of ADD095 Antenna and Fault Rectification,	1	
30.	Installation of ADD095 Antenna and Fault Rectification- Battery replaced & Time server reconfigured, windows re-installed	1	
31.	Installation of ADD095 Antenna and Fault Rectification- DDF205 was reconfigured.	1	
32.	Installation of ADD095 DF Antenna and Fault rectification of wideband DROC	1	
33.	Installation of ADD095 Antenna and Fault Rectification- Server & Laptops reconfigured.	1	
34.	Installation of ADD095 DF Antenna and Fault Rectification of Wideband DROC, Server and Laptops re-installed.	1	
35.	Installation of ADD095 DF Antenna and Fault Rectification of Wideband DROC- Server and Laptops reconfigured.	2	
36.	Installation of ADD095 DF Antenna and Fault Rectification of Wideband DROC	2	