



SUI NORTHERN GAS PIPELINES LIMITED

GAS HOUSE, 21 KASHMIR ROAD, P.O. BOX 56, LAHORE (PAKISTAN)

Ref: PUR-43 (SNT-2076/21)

Dated: 04-03-2022

The Deputy Director (Monitoring & Implementation)

Public Procurement Regulatory Authority,
Cabinet Secretariat,
Cabinet Division, Government of Pakistan,
Federal Bank for Cooperatives Building, Sector G-5/2,
ISLAMABAD
FAX NO. 051-9224823

Dear Sir,

TECHNICAL EVALUATION REPORT (As Per Rule 35 of PP Rules, 2004)

In compliance to Rule 35 of Public Procurement Rules, 2004, we give hereunder evaluation result of bids received against tender enquiry having value Rs.500,000/- and above issued from Sui Northern Gas Pipelines Ltd:-

- | | | |
|----------------------------------|---|---------------------------------------|
| 1. Name of Procuring Agency | : | Sui Northern Gas Pipe Line Limited, |
| 2. Method of Procurement | : | Single Stage Two Envelop System (ICB) |
| 3. Title of Procurement | : | Plug Valves |
| 4. Tender Enquiry No. | : | SNT-2075/21 |
| 5. PPRA Ref. No. (TSE) | : | TS454352E |
| 6. Date & Time of Bid Closing | : | 23-12-2021 at 1530 Hours |
| 7. Date & Time of Bid Opening | : | 23-12-2021 at 1600 Hours |
| 8. No. of Bids Received | : | 04 (Four) |
| 9. Criteria for Bid Evaluation | : | As per tender documents |
| 10. Details of Bid(s) Evaluation | : | As under:- |

Name of Bidder	Technical Marks (if applicable)	Rule/Regulation/SBD*/Policy/ Basis for Technical Rejection / Acceptance as per Rule 35 of PP Rules, 2004
M/s Defence Resource Group, Lahore rep. M/s CDB Engineering S.p.A., Italy	Technically Non-Responsive	Technically non-responsive on account of followings:- 1. Model No. of 6" dia plug valve is ambiguous. 2. Material grades of offered plug valves are not clear. 3. No drawings has been submitted for Ring Type Joint ends. 4. Actual shop drawings were not provided to verify the design. 5. Fire test certificates does not fulfil the criteria defined in 15.1 clause. 6. Model Nos. of fire tested valves are not clear. 7. Not comply to tender clause 3.2 (b) of tender terms.
M/s Rana Traders, Islamabad rep. M/s Zhejiang Flow Tech Machinery Co. Ltd., China	Technically Non-Responsive	Technically non-responsive on account of followings:- 1. Fire Safety certicaite irrelevant to quoted valves. 2. Hydrostatic and Seat Tests of previously manufactured plug valves not provide. 3. Not comply to tender clause 3.2 (b) of tender terms.


Contd. P/2.

Telephones Exch: { +92-42)9082000
+92-42)9082006

Telephones: { +92-42)9085044

Fax: +92-42)9201275

www.sngpl.com.pk



OHSAS 18001 ISO 14001



SUI NORTHERN GAS PIPELINES LIMITED

GAS HOUSE, 21 KASHMIR ROAD, P.O. BOX 56, LAHORE (PAKISTAN)


-2-

M/s Pakmaco (Pvt.) Ltd., Karachi rep. M/s Serck Audco Valves, UK	Technically Responsive	Technically Responsive.
M/s T.H. Syed (Pvt.) Ltd., Lahore rep. M/s Galli & Cassina S.p.A., Italy	Technically Responsive	Technically Responsive.

11. Accordingly, financial bid of the technically responsive bidder will be opened in due course of time.

Thanking you and with best regards.

Yours faithfully,
SUI NORTHERN GAS PIPELINES LIMITED


(AATIR MAHMOOD)
DY. CHIEF OFFICER (PROCUREMENT)
for MANAGING/DIRECTOR

*Standard Bidding Documents (SBD)

COPY BY POST:-

The Deputy Director (Monitoring & Implementation), Islamabad